UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

: 7,011,454 B2

Page 1 of 1

DATED

APPLICATION NO.: 10/647848

INVENTOR(S)

: March 14, 2006 : Jack E. Caveney et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 10,

Line 10, reads "a ring an portion for attaching" should read -- a ring portion for attaching. --.

Column 11,

Line 23, reads "...second cam surface a buffer clamp" should read -- ...second cam surface actuates a buffer clamp --.

Signed and Sealed this

Eleventh Day of July, 2006

JON W. DUDAS
Director of the United States Patent and Trademark Office